












U.S. ARMY CORPS OF ENGINEERS
SACRAMENTO DISTRICT




Legend

-  South Boundary Road 100ft Buffer
-  Fuel Breaks
- Surface MEC Removal Status**
-  To Be Surveyed
-  Surface Field Complete
-  Surface QC Complete
-  Surface QA Complete
-  Surface Removal Completed in 2013

Operations Completed Through: 11/17/2015




FORMER FORT ORD
Unit 23 Surface MEC Removal Status






U.S. ARMY CORPS OF ENGINEERS
SACRAMENTO DISTRICT




Legend



- ⊛ Expended (Destroyed)
- * Live (Destroyed)
- MPPEH (CP)
- MPPEH (LIP)
- ▨ Fuel Breaks
- ▨ Surface Removal Planned
- ▨ No MD
- ▨ < 75 Lbs MD
- ▨ 75-250 Lbs MD
- ▨ 250-500 Lbs MD
- ▨ 500-1000 Lbs MD
- ▨ > 1000 Lbs MD
- ▨ Surface Removal Completed in 2013

Operations Completed Through: 11/17/2015








FORMER FORT ORD
Unit 23 Containment Line MD Density






Legend

-  Fuel Breaks
-  To Be Surveyed
-  Surface Field Complete
-  Surface QC Complete
-  Surface QA Complete


Operations Completed Through: 11/17/2015



U.S. ARMY CORPS OF ENGINEERS
SACRAMENTO DISTRICT




FORMER FORT ORD
Hugo Road Fuel Break
Surface MEC Removal Status



Legend

⌘	Expended (Destroyed)	☐	No MD
⌘	Live (Destroyed)	☐	< 75 Lbs MD
•	MPPEH (CP)	☐	75-250 Lbs MD
•	MPPEH (LIP)	☐	250-500 Lbs MD
☐	Fuel Breaks	☐	500-1000 Lbs MD
		☐	> 1000 Lbs MD

Operations Completed Through: 11/17/2015






**U.S. ARMY CORPS OF ENGINEERS
SACRAMENTO DISTRICT**







**FORMER FORT ORD
Hugo Road Fuel Break MD Density**




Legend

- Fuel Breaks
- To Be Surveyed
- DGM Survey Status**
- Field Collection Complete
- Data Processing Complete
- Data QC Complete
- Data QA Complete


Operations Completed Through: 11/17/2015



FORMER FORT ORD Unit 25 DGM Survey Status




U.S. ARMY CORPS OF ENGINEERS
SACRAMENTO DISTRICT



Legend

- Fuel Breaks
- To Be Surveyed
- DGM Survey Status**
- Field Collection Complete
- Data Processing Complete
- Data QC Complete
- Data QA Complete

Operations Completed Through: 11/17/2015



FORMER FORT ORD
Unit 31 DGM Survey Status