

Table 1. Reuse Parcels Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

California State University, Monterey Bay Brostrom Park Family Housing Area Thorson Village Family Housing Area Monterey Peninsula Unified School District York Road McKinney Homeless Act Parcels University of California, Santa Cruz Haves Park Housing Area Stilwell Housing Area Fritzsche Army Airfield Monterey County Parks Patton Park Housing Area Abrams Park Housing Area City of Marina City of Seaside City of Del Rey Oaks Monterey County Golden Gate University Monterey Institute for Research in Astronomy Pacific Gas and Electric Substation Caltrans Monterey-Salinas Transit Monterey Peninsula College Marina Equestrian Association

Note: The above list is not intended to be all inclusive or to imply priority for parcel transfer. It is subject to change.

York School

Table 2. EBS Points of Contact Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

Fort Ord (Presidio of Monterey-Annex) Points of Contact

\sim	am	А

Mr. Mark Reese
Mr. Mark Reese
Mr. Mark Reese
Ms. Claire Murdo
Ms. Linda Temple
Ms. Linda Temple
Mr. Roy Durham
Mr. Lee Stickler
SFC Beardsley
Chief Fletcher
Ms. Gail Youngblood
Ms. Gail Youngblood

Ms. Barbara Schmitt Mr. Joe Daniels/Ms. Linda Temple

Program

Asbestos Management Program Lead-Based Paint Assessments Radon Surveys

Radon Surveys PCB Transformers

CERFA UXO Surveys Range Control

Former Range Control

Former 49th Fort Ord EOD Unit

Fort Ord Fire Department

RI/FS Program RCRA Program UST Program

Radiological Surveys

COE Points of Contact

Name

Ms. Linda Findley-Miller Mr. Dan McMindes

Program

Asbestos Management Program Underground/Aboveground Storage Tanks

Table 3. Radon Survey Results Draft Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

No buildings within the McKinney Group A Parcels had radon survey results above 4 pCi/L.

pCi/L Picocuries per liter of air.

Table 4. Radiological Surveys in Buildings Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

Building Numbers

Isotope(s) Present

No buildings or areas were identified by Fort Ord for radiological surveys within the McKinney Group A Parcels.

Table 5. Underground Storage Tank Status Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

	UST		Size	Year	Date	Tes	t Res	ults	Closure
Building	No.	Contents	(Gallons)	Placed	Removed	92	91	90	Granted

No underground storage tanks were identified within the McKinney Group A Parcels.

Table 6. Aboveground Storage Tank Status Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

	condarv
Number Contents (Gallons) Berm Con	tainment
Number Contents (Ganons) Bern Con	паншын

No aboveground storage tanks were identified within the McKinney Group A Parcels.

Table 7. Solid Waste Management Units Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

SWMU	SWMU	SWMU		Associated IRP
Site No.	Name	Type	Status	Site No.

No SWMUs were identified within the McKinney Group A Parcels.

Table 8. Definitions of CERFA Categories Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

- CERFA Parcel Portion of the installation real property for which [the CERFA] investigation revealed no evidence of storage for 1 year or more, release, or disposal of CERCLA hazardous substances, petroleum, or petroleum derivatives and no evidence of being threatened by migration of such substances. CERFA parcels include areas where PCB-containing equipment is in operation, but there is not evidence of release. CERFA parcels also include any portion of the installation that once contained related environmental, hazard, or safety issues including unexploded ordnance (UXO) located on firing ranges or impact areas, radon, stored (not in use) PCB-containing equipment, products that contained radionuclides being used for their intended purposes, asbestos contained within building materials, and lead-based paint applied on building material surfaces, but that has since been removed or fully remediated.
- CERFA Parcel with Qualifier(s) A portion of the installation real property for which [the CERFA] investigation reveals no evidence of storage for 1 year or more, release, or disposal of CERCLA hazardous substance, petroleum, or petroleum derivatives and no evidence of being threatened by migration of such substances. The parcel does however contain related environmental, hazard, or safety issues including UXO located on firing ranges or impact areas, radon, radionuclides contained within products being used for their intended purposes, asbestos contained within building materials, lead-based paint applied to building material surfaces, or stored (not in use) PCB-containing equipment.
- CERFA Disqualified Parcel Portion of the installation real property for which [the CERFA] investigation reveals evidence of a release, disposal, or storage for more than 1 year of a CERCLA hazardous substance, petroleum, or petroleum derivative; or a portion of the installation is threatened by such a release or disposal. CERFA disqualified parcels also include any portion of the installation where PCB, asbestos containing material, lead-based paint residue, or any ordnance has been disposed of, and any locations where chemical ordnance has been stored. Additionally, CERFA disqualified parcels include any areas in which CERCLA hazardous substances or petroleum products have been released or disposed and subsequently fully remediated.
- CERFA Excluded Parcel A portion of the installation real property retained by the Department of
 Defense, and therefore not explicitly investigated for CERFA. CERFA-excluded parcels also
 include any portions of the installation that have already been transferred by deed to a party
 outside the federal government, or by transfer assembly to another federal agency. No CERFA
 excluded parcels were identified at Fort Ord.

Source: Arthur D. Little, Inc. (ADL), 1994. Community Environmental Response Facilitation Act (CERFA) Report, Fort Ord, Monterey, California. Contract No. DAAA15-91-D-0016, April 8, Revision 1 (Final).

Table 9. Basewide IRP Site Summary Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

Site Number	Site Name	Category
1	Ord Village Sewage Treatment Plant	No Action
2	Main Garrison Sewage Treatment Plant	Remedial Investigation
3	Beach Trainfire Ranges	Remedial Investigation
4	Beach Stormwater Outfalls	No Action*
5	Range 36A	Remedial Investigation
6	Range 39 (Abandoned Car Dump)	Interim Action
7	Ranges 40 and 41 (Fire Demonstration Area)	No Action
8	Range 49 (Molotov Cocktail Range)	Interim Action
9	Range 39 (FFE Training Area)	Remedial Investigation
10	Burn Pit	Interim Action
11	AAFES Fueling Station	No Action
12	Low Meadow, DOL Yard, Cannibalization Yard	Remedial Investigation
13	Railroad Right-of-Way	No Action
14	707th Maintenance Facility	Interim Action
15	DEH Yard	Interim Action
16	DOL Maintenance Yard and Pete's Pond	Remedial Investigation
17	1400 Block Motor Pool	Remedial Investigation
18	1600 Block Motor Pool	No Action
19	2200 Block Facility	No Action
20	South Parade Ground, 3800 and 519 Motor Pools	Interim Action
21	4400/4500 Block Motor Pool, East	Interim Action
22	4400/4500 Block Motor Pool, West	Interim Action
23	3700 Block Motor Pool Complex	Interim Action
24	Old DEH Yard	Interim Action#
25	Former DRMO	No Action

Table 9. Basewide IRP Site Summary Environmental Baseline Survey McKinney Group A Parcels Former Fort Ord, California

Site Number	Site Name	Category
26	Sewage Pump Stations	No Action
27	Army Reserve Motor Pool	No Action
28	Barracks and Main Garrison Area	No Action
29	DRMO	No Action
30	Drive Training Area	Interim Action
31	Former Dump Site	Remedial Investigation
32	East Garrison Sewage Treatment System	No Action
33	Golf Course	No Action
34	FAAF Fueling Facility	Interim Action
35	FAAF Aircraft Cannibalization Yard	No Action
36	FAAF Sewage Treatment Plant	No Action
37	Trailer Park Maintenance Shop	No Action
38	AAFES Dry Cleaners	No Action
39	Impact Area	Remedial Investigation
40	FAAF Helicopter Defueling Areas	Interim Action#
41	Crescent Bluff Fire Drill Area	Interim Action#

[#] Site categories may change as additional information is received from ongoing investigation.

^{*} Site 4, the Beach Stormwater Outfalls, was categorized as a No Action site because it was investigated under the Basewide Surface Water Outfall Investigation.

	Site Name	Location	Site Description
	IRP Sites		
-	Subparcel A-1		
_	Site 2: Main Garrison Sewage Treatment Plant	0.27 mile west	Soil and groundwater contamination: lead in soil, chlorinated solvents in groundwater
	Site 3: Beach Trainfire Area	0.27 mile west	Soil contamination: metals
_	Site 4: Beach Stormwater Outfalls	0.57 mile west	No unacceptable risk associated with chemicals in soil or groundwater
-	Site 13: Railroad Right-of-way	0.19 mile northwest	No unacceptable risk associated with chemicals in soil or groundwater
	Site 14: 707th Maintenance Facility	0.76 mile south	Soil contamination: hydrocarbons
-	Site 15: DEH Yard	0.63 mile southeast	Soil contamination: pesticides
_	Site 16: DOL Maintenance Yard and Pete's Pond	0.55 mile south	Soil contamination: TPH, BTEX, VOCs, metals, landfill debris (UXO)
	Site 17: 1400 Block Motor Pool	0.20 mile south	Soil contamination: medical waste, metals, TPH, low dioxins
_	Site 18: 1600 Block Motor Pool	0.28 mile south	No unacceptable risk associated with chemicals in soil or groundwater
_	Site 19: 2200 Block Facility	0.15 mile south	Soil contamination: chlordane, unknown hydrocarbons
-	Site 20: South Parade Ground, 3800 & 519th Motor Pools	0.8 mile south	Soil contamination: low chromium, organics in soil gas, potential landfill locations
-	Site 25: Former DRMO Site	0.38 mile south	No unacceptable risk associated with chemicals in soil or groundwater
_	Site 38: AAFES Dry Cleaners	0.57 mile south	No unacceptable risk associated with chemicals in soil or groundwater
	Operable Unit 2, Fort Ord Landfills	0.63 mile southeast	Soil and groundwater contamination: TCE, landfi debris
-	Subparcel A-2		
-	Site 26: Sewage Pump Stations	200 feet southeast	No unacceptable risk associated with chemicals in soil or groundwater
	Site 27: Army Reserve Motor Pool	0.3 mile east	No unacceptable risk associated with chemicals in soil or groundwater

Harding Lawson Associates

C37658-H May 30, 1995 Version 1 1 of 5

_	Site Name	Location	Site Description
_	Site 34: FAAF Fueling Facility	0.23 mile northeast	Soil contamination: hydrocarbons
	Site 35: Aircraft Cannibalization Yard	0.38 mile north	No unacceptable risk associated with chemicals in soil or groundwater
-	Site 40: FAAF Defueling Area	0.6 mile north	Soil contamination: methane, VOCs, hydrocarbons, unknown hydrocarbons
_	Operable Unit 1	0.5 mile north	Soil and groundwater contamination: hydrocarbons, solvents; remediation being conducted by Fort Ord
-	Operable Unit 2, Fort Ord Landfills	0.3 mile south	Soil and groundwater contamination: TCE, landfill debris
	Potential OEW Locations (USAEDH Site	No.)	
	Subparcel A-1		
<u> </u>	Beach Trainfire Ranges (No. 22)	0.7 mile west	Sampling completed; no OEW removal action recommended
,	Mortar Square 1 (NA)	0.5 mile northwest	Need for further investigation being evaluated
	Mortar Square 2 (NA)	0.4 mile north	Need for further investigation being evaluated
	Mortar Square 3 (NA)	0.4 mile north	Need for further investigation being evaluated
	Mine & Booby Trap Area 1 (No. 6)	0.5 mile northwest	Sampling completed, no OEW removal action recommended
	Flame Thrower Range 1 (No. 1)	0.4 mile north	Sampling completed, no OEW removal action recommended
	75-mm Pack Howitzer Firing Area (NA)	0.4 mile northwest	Need for further investigation being evaluated
	Storage Yard Landmine (NA)	0.4 mile south	Need for further investigation being evaluated
	Pete's Pond (No. 2)	0.6 mile southeast	Sampling completed, no OEW removal action recommended
	Subparcel A-2		
	Machine Gun Proficiency Training Area (NA)	0.89 mile southwest	Need for further investigation being evaluated
	Imjin Road Practice Mortar Range (No. 13A)	0.28 mile southwest	Sampling completed, no OEW removal action recommended
_			

Site Name	Location	Site Description
Solid Waste Management Unit (SWMU) Locations	
Subparcel A-1		
FTO-002 Fort Ord Sanitary Landfill	0.71 mile east	Soil and groundwater contamination; TCE, landfil debris
FTO-004 707th Maintenance Bn, A, B, and C Co. Motorpools	0.83 mile southeast	Temporary container storage, no evidence of releases
FTO-007 Cannibalization Area	300 feet northwest	Storage yard for deadlined vehicles and vehicle parts
FTO-012 Main Garrison Sewage Treatment Plant	0.28 mile west	Facility shut down in 1989, documented soil and groundwater contamination onsite
FTO-013 Building 1442 Autoclave	0.47 mile south	Thermal treatment unit, no evidence of releases
FTO-015 PCB Storage Area	0.72 mile south	Transformer storage area, no evidence of releases
FTO-017 TASC Plastic Shop	0.31 mile southeast	Container storage area, no evidence of releases
FTO-018 Pesticide Mixing Area	0.37 mile southeast	Mixing area, no evidence of releases
FTO-019 AAFES Economy Cleaners	0.60 mile south	1,000 gallon UST, no evidence of releases
FTO-022 Abandoned DRMO Site	0.45 mile south	Abandoned storage site, no evidence of releases
FTO-023 TASC Graphics Shop	0.31 mile south	Temporary container storage, no evidence of releases
FTO-036 DOL Heavy Equipment Maintenance Motorpool	0.64 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-037 DOL Main Automotive Yard Pool	0.15 mile northwest	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-038 DOL General Equipment Maintenance Yard	200 feet northwest	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-040 DOL Temporary	0.51 mile southeast	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-041 590th SS Company Motorpool	0.28 mile southeast	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-044 121st Aviation Bn., Co. E	0.64 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases

_	Site Name	Location	Site Description
	FTO-045 237th Medical Detachment Motorpool	0.64 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
,	FTO-048 6th/8th Field Artillery Bn.	0.61 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
	FTO-049 7/15th Field Artillery Bn.	0.70 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
<u></u>	FTO-050 7/7th Air Defense Artillery	0.70 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
	FTO-051 5/15th Field Artillery Bn.	0.70 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
_	FTO-052 2/62nd ADA B-Battery	0.68 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
	FTO-053 7th Medical Bn.	0.47 mile southeast	Temporary container storage for used vehicle lubricants, no evidence of releases
	FTO-056 7th MP Company	0.68 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
_	FTO-057 571st MP Company	0.31 mile south	Temporary container storage for used vehicle lubricants, no evidence of releases
	FTO-058 761st Chemical Company	0.38 mile southeast	Temporary container storage for used vehicle lubricants, no evidence of releases
	Subparcel A-2		
	FTO-001 Abandoned Fire Training Pit	0.49 mile north	Groundwater currently being remediated by HLA
_	FTO-002 Fort Ord Sanitary Landfill	0.48 mile southwest	Soil and groundwater contamination; TCE, landfill debris
	FTO-006 HHC Cavalry Regiment Motorpool, Bldg. 527	0.56 mile northeast	Container storage, no longer in existence
_	FTO-039 DOL Aircraft Maintenance Pool	0.60 mile north	Temporary container storage for used vehicle lubricants, no evidence of releases
	FTO-043 1-123rd AUN Regiment Motorpool	0.56 mile northeast	Temporary container storage for used vehicle lubricants, no evidence of releases
	FTO-046 214th Cavalry Reconnaissance Flight Motorpool	0.57 mile northeast	Temporary container storage for used vehicle lubricants, no evidence of releases
	Motorpool, Bldg. 527 FTO-039 DOL Aircraft Maintenance Pool FTO-043 1-123rd AUN Regiment Motorpool FTO-046 214th Cavalry Reconnaissance	0.60 mile north 0.56 mile northeast	Container storage, no longer in existence Temporary container storage for used vehicle lubricants, no evidence of releases Temporary container storage for used vehicle lubricants, no evidence of releases Temporary container storage for used vehicle

	Site Name	Location	Site Description
_	FTO-047 3rd Bn. 123rd AUN Brigade Motorpool	0.5 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases
, —	FTO-055 U.S. Army Reserve Center Motorpool	0.30 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases

This site is being addressed under the NPL program as Operable Unit 1. Soil remediation is complete, groundwater remediation is in progress.

__ (NA) No corresponding USAEDH Site No. available.