APPENDIX C ASBESTOS SURVEY HISTORY MCKINNEY GROUP C PARCELS

ASBESTOS SURVEY HISTORY M KINNEY GROUP C PARCELS

The following tables were prepared for this EBS document by ATC Environmental, Inc. (ATC; formerly DEI), on behalf of Fort Ord and HLA. In July 1995, HLA gave ATC a list of buildings within the McKinney Group C Parcel defined by the Army and requested that ATC provide (in tabular format) information about each building. ATC is performing asbestos surveys of buildings at Fort Ord independently of this EBS project. The following is a complete listing of ATC's Priority Rating System Codes and corresponding recommended response actions:

- 1 Immediate total removal recommended
- 2 Immediate repair, short-term removal recommended
- 3 Immediate repair, long-term removal recommended
- 4 Immediate repair, management with 6-month inspection cycle recommended
- 5 Immediate repair, management with 1-year inspection cycle recommended
- 6 Short-term repair, long-term removal recommended
- 7 Short-term repair, management with 6-month inspection cycle recommended
- 8 Short-term repair, management with 1-year inspection cycle recommended
- 9 Short-term repair, management with 2-year inspection cycle (biannual) recommended
- 10 Long-term removal recommended
- 11 Management with 6-month inspection cycle recommended
- 12 Management with 1-year inspection cycle recommended
- 13 Management with 2-year inspection cycle (biannual) recommended.

The building lists in the table are building numbers identified from Fort Ord base maps and interviews with Fort Ord personnel. Possible sources of error in the building lists include:

- Structures with numbers on a map that either are not buildings (e.g., flagpoles, loading docks) or have been demolished. Where possible, these have been identified in the table
- Structures that do not appear on available maps. Where possible, such buildings have been identified by comparing the ATC asbestos survey summary with a building list; however, structures within the parcel that were part of ATC's survey scope may not appear on the base map
- Structures incorrectly numbered on a base map
- Margin of error in current definition of parcel boundaries.

McKINNEY HOMELESS ACT - VIETNAM VETS OF MONTEREY COUNTY **ASBESTOS SURVEY HISTORY**

| , | B | JILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | LOWEST RATING ASSIGNED | NONFRIABLE ACM | LOWEST RATING ASSIGNED | NO ACM |
|---|---|---------|-------------------|----------|----------------|------------------------------|-------------------|------------------------------|--------------|
| | Р | 02798 | 1941 | Y | Υ | 5 | Υ | 5 | - |
| | τ | 02988 | 1942 | Y | N | _ | Y | 13 | _ |
| | T | 02990 | 1941 | Υ | N | - | Υ | 2 | _ |
| | Р | 08704 | 1962 | Y | Y | 12 | Υ | 13 | _ |
| | ₽ | 08705 | 1962 | Υ | Y | 12 | Υ | 13 | - |
| | P | 08706 | 1962 | Y | Υ | 12 | Y | 13 | _ |
| | Р | 08707 | 1962 | Y | Y | 12 | Y | 13 | _ |
| | P | 08708 | 1962 | Y | Υ | 12 | Υ | 13 | ~ |
| | P | 08717 | 1962 | Y | Υ | 12 | Υ | 13 | - |
| - | Р | 08718 | 1962 | Y | Y | 12 | Υ | 13 | _ |
| | P | 08719 | 1962 | Y | Υ | 12 | Υ | 13 | - |
| _ | Р | 08720 | 1962 | Y | Υ | 10 | Υ | 13 | _ |
| | P | 08721 | 1962 | Y | Y | 12 | Υ | 13 | _ |
| | Ρ | 08722 | 1962 | Y | Y | 12 | Υ | 13 | |
| - | Р | 08723 | 1962 | Υ | Υ | 10 | Υ | 13 | _ |
| | P | 08724 | 1962 | Y | Υ | 10 | Υ | 9 | ~ |
| - | Р | 08725 | 1962 | Y | Υ | 12 | Υ | 9 | - |
| | P | 08726 | 1962 | Y | Υ | 12 | Υ | 9 | - |
| | P | 08727 | 1962 | Y | Υ | 9 | Y | 9 | - |
| | Р | 08736 | 1962 | Y | Y | 12 | Υ | 13 | - |
| | Р | 08737 | 1962 | Y | Υ | 12 | Υ | 13 | - |
| | Ρ | 08738 | 1962 | Y | Υ | 12 | Υ | 13 | _ |
| | P | 08739 | 1962 | Y | Υ | 12 | Υ | 13 | - |
| - | P | 08740 | 1962 | Y | Υ | 12 | Υ | 13 | - |
| | Р | 08741 | 1962 | Y | Y | 10 | Y | 13 | _ |
| | P | 08742 | 1962 | Υ | Y | 12 | Y | 13 | - |
| | | | | | | | | | |

LEGEND: IP = In progress

Y = Yes

N = No

U = Unknown

X = Applicable

- = Not applicable

ACM = Asbestos-containing material

Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

^{*} Not a structure/No survey performed ** Unknown structure/No building found

McKINNEY HOMELESS ACT - HOUSING AUTHORITY OF MONTEREY COUNTY ASBESTOS SURVEY HISTORY

| , <u>-</u> | В | JILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | LOWEST RATING ASSIGNED | NONFRIABLE ACM | LOWEST RATING ASSIGNED | NO ACM |
|------------|---|---------|-------------------|----------|----------------|------------------------------|-------------------|------------------------------|-----------|
| | T | 02793 | 1940 | Y | N | - | Y | 13 | |
| | Ţ | 02795 | 1940 | Y | N | - | Υ | 13 | _ |
| | τ | 02797 | 1940 | Y | Y | 12 | Υ | 13 | - |
| | Ρ | 06234 | 1980 | Y | N | ~ | Υ | 13 | - |
| | P | 06235 | 1980 | Υ | N | - | Y | 13 | - |
| , marine | P | 06237 | 1980 | Y | N | - | Y | 13 | - |
| | Р | 06238 | 1980 | Y | N | - | Y | 13 | - |
| | Р | 06239 | 1980 | Y | N | - | Υ | 13 | - |
| _ | P | 06240 | 1980 | Y | N | - | Υ | 13 | - |
| | Р | 06241 | 1980 | Y | N | - | Υ | 13 | _ |
| | P | 06242 | 1980 | Υ | N | - | Y | 13 | - |
| <u>,</u> | Ρ | 06245 | 1980 | Y | N | _ | Y | 13 | - |
| | Р | 06246 | 1982 | Υ | N | - | Y | 13 | ~ |
| | | | | | | | | | |

LEGEND: IP = In progress

Y = Yes

N = No

U = Unknown

X = Applicable

- = Not applicable

ACM = Asbestos-containing material

Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

^{*} Not a structure/No survey performed

^{**} Unknown structure/No building found

McKINNEY HOMELESS ACT - INTERIM, INC. **ASBESTOS SURVEY HISTORY**

| | BUILDING | | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | LOWEST RATING ASSIGNED | LOWEST NONFRIABLE RATING ACM ASSIGNED | | NO ACM | |
|---|----------|-------|-------------------|----------|----------------|------------------------------|---|----|-----------|--|
| | Р | 06111 | 1978 | Y | N | - | Y | 9 | <u>-</u> | |
| _ | Р | 06112 | 1978 | Y | N | _ | Y | 13 | - | |
| | P | 06113 | 1978 | Υ | N | _ | Y | 13 | - | |
| | Р | 06114 | 1978 | Υ | N | _ | Y | 9 | - | |

LEGEND: IP = In progress

N = No

X = Applicable

1

Y = Yes

- = Not applicable

U = Unknown

ACM = Asbestos-containing material Rating 1-5 = ACM of immediate concern * Not a structure/No survey performed ** Unknown structure/No building found

HLA PROJECT NO. 25894