

APPENDIX C
ASBESTOS SURVEY HISTORY

CSUMB PARCEL - ASBESTOS SURVEY HISTORY

The following table was prepared by ATC on behalf of Fort Ord and HLA for this EBS document. In January 1994, HLA gave ATC a list of buildings within the CSUMB parcel defined by the Army and requested that ATC provide (in tabular format) the information shown in the table headings. ATC is performing asbestos surveys of buildings at Fort Ord independently of this EBS project.

The building list is based on building numbers gathered from Fort Ord base maps and interviews with Fort Ord personnel. Possible sources of error in the building list include:

- Structures that do not appear on available maps - where possible, such buildings have been identified by comparing the ATC asbestos survey summary with a building list; however, there may be structures within the parcel that are not on the base map and were not part of ATC's survey scope.
 - Structures incorrectly numbered on a base map
 - Margin of error in current definition of parcel boundaries
- Structures with numbers on a map that either are not buildings (e.g., flagpoles, loading docks) or have been demolished - where possible, these have been identified in the table

CSU PARCEL 1 – ASBESTOS SURVEY HISTORY

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| T 01008 ** | U | N | U | U | U | U | U |
| T 01009 | 1941 | Y | Y | N | Y | Y | - |
| T 01010 | 1941 | Y | N | - | Y | Y | - |
| T 01011 | 1940 | Y | N | - | Y | Y | - |
| T 01012 | 1940 | Y | Y | N | Y | Y | - |
| T 01030 | 1941 | Y | N | - | Y | Y | - |
| T 01031 | 1941 | Y | N | - | Y | N | - |
| S 01032 | 1968 | Y | Y | N | Y | Y | - |
| S 01033 | 1968 | Y | N | - | Y | Y | - |
| T 01101 ** | U | N | U | U | U | U | U |
| T 01102 ** | U | N | U | U | U | U | U |
| T 01103 ** | U | N | U | U | U | U | U |
| T 01104 ** | U | N | U | U | U | U | U |
| T 01120 | 1940 | Y | N | - | Y | N | - |
| T 01121 ** | U | N | U | U | U | U | U |
| T 01122 ** | U | N | U | U | U | U | U |
| T 01123 ** | U | N | U | U | U | U | U |
| T 01124 ** | U | N | U | U | U | U | U |
| T 01136 | 1941 | Y | Y | N | Y | N | - |
| T 01140 | 1940 | Y | N | - | Y | Y | - |
| T 01141 ** | U | N | U | U | U | U | U |
| T 01142 ** | U | N | U | U | U | U | U |
| T 01143 ** | U | N | U | U | U | U | U |
| T 01144 ** | U | N | U | U | U | U | U |
| T 01160 | 1941 | Y | N | - | Y | Y | - |
| T 01161 ** | U | N | U | U | U | U | U |
| T 01162 ** | U | N | U | U | U | U | U |
| T 01163 ** | U | N | U | U | U | U | U |
| T 01164 ** | U | N | U | U | U | U | U |
| T 01176 | 1941 | Y | N | - | Y | N | - |
| T 01180 | 1940 | Y | N | - | Y | N | - |
| T 01181 ** | U | N | U | U | U | U | U |
| T 01182 ** | U | N | U | U | U | U | U |
| T 01183 ** | U | N | U | U | U | U | U |
| T 01184 ** | U | N | U | U | U | U | U |
| T 01196 | 1941 | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| T 01198 ** | U | N | U | U | U | U | U |
| T 01201 ** | U | N | U | U | U | U | U |
| T 01202 ** | U | N | U | U | U | U | U |
| T 01203 ** | U | N | U | U | U | U | U |
| P 01220 | 1970 | Y | N | - | Y | N | - |
| T 01221 ** | U | N | U | U | U | U | U |
| P 01225 ** | U | N | U | U | U | U | U |
| T 01283 ** | U | N | U | U | U | U | U |
| T 01285 ** | U | N | U | U | U | U | U |
| T 01286 ** | U | N | U | U | U | U | U |
| S 01287 | 1974 | Y | N | - | N | - | X |
| T 01288 | 1961 | Y | N | - | Y | Y | - |
| T 01421 | 1940 | Y | N | - | Y | N | - |
| T 01422 | 1940 | Y | N | - | Y | N | - |
| T 01423 | 1940 | Y | N | - | Y | N | - |
| T 01424 | 1940 | Y | N | - | Y | N | - |
| T 01425 | 1940 | Y | N | - | Y | N | - |
| T 01426 | 1940 | Y | Y | N | Y | N | - |
| T 01427 | 1940 | Y | N | - | Y | N | - |
| T 01428 | 1940 | Y | N | - | Y | N | - |
| T 01429 | 1940 | Y | N | - | Y | N | - |
| T 01430 | 1940 | Y | N | - | Y | N | - |
| T 01431 | 1940 | Y | N | - | Y | N | - |
| T 01432 | 1940 | Y | N | - | Y | N | - |
| T 01433 | 1940 | Y | N | - | Y | N | - |
| T 01434 | 1940 | Y | N | - | Y | N | - |
| T 01435 | 1940 | Y | N | - | Y | N | - |
| T 01436 | 1940 | Y | N | - | Y | N | - |
| T 01437 | 1940 | Y | N | - | Y | N | - |
| T 01438 | 1940 | Y | N | - | Y | N | - |
| T 01439 | 1941 | Y | N | - | Y | N | - |
| T 01440 | 1941 | Y | N | - | Y | N | - |
| T 01441 | 1941 | Y | N | - | Y | N | - |
| P 01442 | 1940 | Y | N | - | Y | N | - |
| T 01443 | 1941 | Y | N | - | Y | N | - |
| T 01444 ** | U | N | U | U | U | U | U |
| T 01445 ** | U | N | U | U | U | U | U |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| T 01446 ** | U | N | U | U | U | U | U |
| T 01447 ** | U | N | U | U | U | U | U |
| T 01448 ** | U | N | U | U | U | U | U |
| T 01449 | 1940 | Y | N | - | Y | N | - |
| T 01450 | 1941 | Y | N | - | Y | N | - |
| T 01451 | 1941 | Y | N | - | Y | N | - |
| T 01452 ** | U | N | U | U | U | U | U |
| T 01453 | 1941 | Y | N | - | Y | N | - |
| T 01454 | 1941 | Y | N | - | Y | N | - |
| T 01455 | 1941 | Y | N | - | Y | N | - |
| T 01456 | 1941 | Y | N | - | Y | N | - |
| T 01457 | 1941 | Y | N | - | Y | N | - |
| T 01458 | 1941 | Y | N | - | Y | N | - |
| T 01459 | 1941 | Y | N | - | Y | N | - |
| T 01460 | 1941 | Y | N | - | Y | N | - |
| T 01461 | 1941 | Y | N | - | Y | N | - |
| T 01462 | 1941 | Y | N | - | Y | N | - |
| T 01463 ** | U | N | U | U | U | U | U |
| T 01464 ** | U | N | U | U | U | U | U |
| T 01465 | 1941 | Y | Y | Y | Y | Y | - |
| T 01466 | 1941 | Y | N | - | Y | N | - |
| T 01467 | 1941 | Y | N | - | Y | N | - |
| T 01468 | 1967 | Y | N | - | N | - | X |
| P 01480 * | U | N | U | U | U | U | U |
| P 01481 | 1977 | Y | N | - | Y | N | - |
| P 01482 * | U | N | U | U | U | U | U |
| P 01483 | 1977 | Y | N | - | Y | N | - |
| P 01484 * | U | N | U | U | U | U | U |
| P 01485 * | U | N | U | U | U | U | U |
| P 01486 | 1977 | Y | N | - | Y | N | - |
| P 01487 * | U | N | U | U | U | U | U |
| P 01488 * | U | N | U | U | U | U | U |
| P 01489 | 1977 | Y | N | - | Y | N | - |
| P 01490 * | U | N | U | U | U | U | U |
| P 01491 | 1977 | Y | N | - | Y | N | - |
| P 01492 * | U | N | U | U | U | U | U |
| P 01493 | 1977 | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 01494 * | U | N | U | U | U | U | U |
| P 01495 | 1977 | Y | N | - | Y | N | - |
| P 01496 * | U | N | U | U | U | U | U |
| P 01497 | 1977 | Y | N | - | Y | N | - |
| T 01501 ** | U | N | U | U | U | U | U |
| T 01502 ** | U | N | U | U | U | U | U |
| 01516 ** | U | N | U | U | U | U | U |
| T 01518 ** | U | N | U | U | U | U | U |
| T 01519 ** | U | N | U | U | U | U | U |
| T 01521 ** | U | N | U | U | U | U | U |
| T 01522 ** | U | N | U | U | U | U | U |
| T 01523 ** | U | N | U | U | U | U | U |
| T 01539 ** | U | N | U | U | U | U | U |
| T 01541 ** | U | N | U | U | U | U | U |
| T 01542 ** | U | N | U | U | U | U | U |
| T 01543 ** | U | N | U | U | U | U | U |
| T 01544 ** | U | N | U | U | U | U | U |
| T 01561 ** | U | N | U | U | U | U | U |
| T 01562 ** | U | N | U | U | U | U | U |
| T 01563 ** | U | N | U | U | U | U | U |
| T 01564 ** | U | N | U | U | U | U | U |
| T 01565 ** | U | N | U | U | U | U | U |
| T 01581 ** | U | N | U | U | U | U | U |
| T 01582 ** | U | N | U | U | U | U | U |
| T 01598 | 1940 | Y | N | - | Y | N | - |
| S 01599 | 1968 | Y | N | - | Y | Y | - |
| T 01601 ** | U | N | U | U | U | U | U |
| T 01602 ** | U | N | U | U | U | U | U |
| T 01603 ** | U | N | U | U | U | U | U |
| T 01622 ** | U | N | U | U | U | U | U |
| T 01624 ** | U | N | U | U | U | U | U |
| P 01638 | 1980 | Y | N | - | Y | N | - |
| T 01640 | 1941 | Y | N | - | Y | N | - |
| T 01641 | 1941 | Y | N | - | Y | N | - |
| T 01642 | 1941 | Y | N | - | Y | N | - |
| T 01643 | 1941 | Y | N | - | Y | N | - |
| T 01644 ** | U | N | U | U | U | U | U |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| T 01645 ** | U | N | U | U | U | U | U |
| T 01646 | 1941 | Y | N | - | Y | N | - |
| T 01647 | 1941 | Y | N | - | Y | N | - |
| T 01648 ** | U | N | U | U | U | U | U |
| T 01649 | 1941 | Y | N | - | Y | N | - |
| T 01650 | 1941 | Y | N | - | Y | Y | - |
| T 01652 ** | U | N | U | U | U | U | U |
| S 01653 | 1974 | Y | N | - | N | - | X |
| T 01654 | 1941 | Y | N | - | Y | N | - |
| T 01655 | 1941 | Y | N | - | Y | N | - |
| T 01656 | 1941 | Y | N | - | Y | N | - |
| T 01657 ** | U | N | U | U | U | U | U |
| T 01660 | 1941 | Y | N | - | Y | N | - |
| P 01661 | 1985 | Y | N | - | Y | N | - |
| 01662 ** | U | N | U | U | U | U | U |
| T 01663 | 1941 | Y | N | - | Y | N | - |
| T 01665 | 1941 | Y | N | - | Y | N | - |
| T 01666 | 1941 | Y | N | - | Y | N | - |
| T 01667A | 1941 | Y | N | - | Y | N | - |
| T 01668 | 1941 | Y | N | - | N | - | X |
| S 01669 | 1944 | Y | N | - | N | - | X |
| S 01671A | 1941 | Y | N | - | Y | N | - |
| T 01672 | 1941 | Y | N | - | Y | N | - |
| T 01673 * | U | N | U | U | U | U | U |
| T 01674 | 1941 | Y | Y | Y | Y | N | - |
| S 01675 | 1974 | Y | N | - | N | - | X |
| T 01676 | 1941 | Y | N | - | N | - | X |
| T 01677 | 1956 | Y | N | - | Y | N | - |
| T 01683 | 1941 | Y | N | - | N | - | X |
| P 01687 * | U | N | U | U | U | U | U |
| P 01697 | 1980 | Y | N | - | Y | N | - |
| P 01698 | U | Y | N | - | N | - | X |
| P 01699 | U | Y | N | - | N | - | X |
| 03176 ** | U | N | U | U | U | U | U |
| P 03575 | 1984 | Y | N | - | Y | N | - |
| P 03576 | 1982 | Y | N | - | Y | N | - |
| P 03578 | 1982 | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 03579 | 1982 | Y | N | - | Y | N | - |
| P 03580 | 1982 | Y | N | - | Y | N | - |
| P 03581 | 1982 | Y | N | - | Y | N | - |
| P 03582 | 1982 | Y | N | - | Y | N | - |
| P 03585 | 1983 | Y | N | - | Y | N | - |
| P 03589 | 1982 | Y | N | - | Y | N | - |
| P 03591 | 1982 | Y | N | - | Y | N | - |
| P 03592 | 1982 | Y | N | - | Y | N | - |
| P 03593 | 1982 | Y | N | - | Y | N | - |
| P 03594 | 1982 | Y | N | - | Y | N | - |
| P 03595 | 1982 | Y | N | - | Y | N | - |
| P 03599 | 1982 | Y | N | - | Y | N | - |
| P 03619 * | U | N | U | U | U | U | U |
| P 03620 | 1977 | Y | N | - | Y | N | - |
| P 03621 | 1977 | Y | N | - | Y | N | - |
| P 03622 | 1977 | Y | N | - | Y | N | - |
| P 03623 | 1977 | Y | N | - | Y | N | - |
| P 03624 | 1978 | Y | N | - | Y | N | - |
| P 03625 | 1978 | Y | N | - | Y | N | - |
| P 03627 | 1978 | Y | N | - | Y | N | - |
| P 03628 | 1978 | Y | N | - | Y | N | - |
| P 03629 | 1978 | Y | N | - | Y | N | - |
| P 03630 | 1978 | Y | N | - | Y | N | - |
| P 03631 | 1978 | Y | Y | N | Y | N | - |
| P 03632 | 1978 | Y | Y | N | Y | N | - |
| P 03634 | 1978 | Y | N | - | Y | N | - |
| P 03635 | 1978 | Y | N | - | Y | N | - |
| P 03636 | 1978 | Y | N | - | Y | N | - |
| P 03637 | 1978 | Y | N | - | Y | N | - |
| P 03638 | 1978 | Y | N | - | Y | N | - |
| P 03640 | 1977 | Y | N | - | Y | N | - |
| P 03641 | 1978 | Y | N | - | Y | N | - |
| P 03642 | 1978 | Y | N | - | Y | N | - |
| P 03643 | 1978 | Y | N | - | Y | N | - |
| P 03644 * | U | N | U | U | U | U | U |
| T 03659 ** | U | N | U | U | U | U | U |
| T 03664 ** | U | N | U | U | U | U | U |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| T 03665 ** | U | N | U | U | U | U | U |
| T 03666 ** | U | N | U | U | U | U | U |
| T 03667 ** | U | N | U | U | U | U | U |
| T 03668 ** | U | N | U | U | U | U | U |
| T 03669 ** | U | N | U | U | U | U | U |
| T 03670 ** | U | N | U | U | U | U | U |
| T 03671 ** | U | N | U | U | U | U | U |
| T 03672 ** | U | N | U | U | U | U | U |
| T 03673 ** | U | N | U | U | U | U | U |
| T 03674 ** | U | N | U | U | U | U | U |
| T 03675 ** | U | N | U | U | U | U | U |
| T 03676 ** | U | N | U | U | U | U | U |
| T 03677 ** | U | N | U | U | U | U | U |
| P 03700 | 1964 | Y | Y | N | Y | Y | - |
| P 03701 | 1955 | Y | N | - | Y | N | - |
| P 03702 | 1958 | Y | Y | N | Y | N | - |
| P 03703 | 1962 | Y | Y | N | Y | N | - |
| P 03705 | 1983 | Y | N | - | Y | N | - |
| P 03707 | 1984 | Y | N | - | N | - | X |
| P 03708 | 1954 | Y | N | - | Y | Y | - |
| T 03709 | 1941 | Y | N | - | Y | N | - |
| T 03710 | 1941 | Y | N | - | N | - | X |
| T 03710A | U | Y | N | - | N | - | X |
| P 03711 | 1954 | Y | N | - | Y | Y | - |
| T 03714 ** | U | N | U | U | U | U | U |
| T 03717 | 1942 | Y | N | - | Y | N | - |
| P 03719 | 1954 | Y | N | - | Y | N | - |
| T 03722 | 1941 | Y | N | - | Y | Y | - |
| P 03723 | 1984 | Y | N | - | Y | N | - |
| P 03725 | 1981 | Y | N | - | Y | N | - |
| T 03742 | 1941 | Y | N | - | Y | Y | - |
| T 03753 | 1958 | Y | N | - | Y | N | - |
| T 03754 | 1963 | Y | N | - | Y | N | - |
| T 03762 | 1941 | Y | N | - | Y | Y | - |
| T 03765 ** | U | N | U | U | U | U | U |
| S 03766 | 1941 | Y | N | - | N | - | X |
| T 03767 | 1941 | Y | N | - | Y | Y | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 03768 * | U | N | U | U | U | U | U |
| T 03769 * | U | N | U | U | U | U | U |
| S 03770 | 1941 | Y | N | - | N | - | X |
| S 03771 | 1941 | Y | N | - | N | - | X |
| T 03772 | 1941 | Y | N | - | Y | N | - |
| S 03775 | 1941 | Y | N | - | N | - | X |
| S 03776 | 1941 | Y | N | - | Y | N | - |
| T 03777 | 1941 | Y | N | - | Y | N | - |
| T 03778 | U | Y | N | - | Y | N | - |
| S 03780 | 1966 | Y | N | - | Y | N | - |
| T 03783 | 1956 | Y | N | - | Y | N | - |
| P 03785 * | U | N | U | U | U | U | U |
| T 03803 | 1942 | Y | N | - | Y | N | - |
| T 03814 ** | U | N | U | U | U | U | U |
| T 03843 | 1957 | Y | N | - | N | - | X |
| T 03845 | 1946 | Y | N | - | Y | Y | - |
| S 03855 | 1961 | Y | N | - | Y | N | - |
| S 03856 | 1961 | Y | N | - | Y | N | - |
| S 03857 | 1961 | Y | N | - | Y | N | - |
| S 03858 | 1961 | Y | N | - | Y | N | - |
| T 03864 ** | U | N | U | U | U | U | U |
| T 03866 ** | U | N | U | U | U | U | U |
| T 03867 | 1943 | Y | N | - | Y | N | - |
| P 03868 * | U | N | U | U | U | U | U |
| T 03871 | 1942 | Y | N | - | Y | N | - |
| T 03872 | 1943 | Y | N | - | Y | N | - |
| P 03873 * | U | N | U | U | U | U | U |
| T 03875 | 1943 | Y | N | - | Y | N | - |
| T 03893A * | U | N | U | U | U | U | U |
| P 03895 | 1966 | Y | Y | N | Y | Y | - |
| S 03897 | 1957 | Y | N | - | Y | N | - |
| S 03898 | 1957 | Y | Y | Y | Y | Y | - |
| P 04426 | 1977 | Y | N | - | Y | N | - |
| P 04521 * | U | N | U | U | U | U | U |
| P 04524 * | U | N | U | U | U | U | U |
| P 04525 | 1953 | Y | N | - | N | - | X |
| P 04526 | 1953 | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|-----------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 04527 | 1953 | Y | N | - | Y | N | - |
| S 04527A | U | Y | N | - | Y | N | - |
| P 04528 | 1981 | Y | N | - | Y | N | - |
| P 04529 * | U | N | U | U | U | U | U |
| P 04530 | 1953 | Y | N | - | Y | N | - |
| S 04530A | U | Y | N | - | Y | N | - |
| P 04531 | 1953 | Y | N | - | Y | N | - |
| P 04532 * | U | N | U | U | U | U | U |
| P 04533 * | U | N | U | U | U | U | U |
| P 04534 | 1953 | Y | N | - | Y | N | - |
| P 04535 * | U | N | U | U | U | U | U |
| P 04536 | 1958 | Y | Y | N | Y | N | - |
| S 04536A | U | Y | N | - | Y | N | - |
| P 04537 | 1958 | Y | Y | N | Y | N | - |
| S 04537A | U | Y | N | - | Y | N | - |
| P 04538 | 1977 | Y | N | - | Y | N | - |
| P 04539 * | U | N | U | U | U | U | U |
| P 04540 * | U | N | U | U | U | U | U |
| P 04541 | 1977 | Y | N | - | N | - | X |
| P 04542 * | U | N | U | U | U | U | U |
| P 04543 * | U | N | U | U | U | U | U |
| P 04544 | 1977 | Y | N | - | Y | N | - |
| P 04545 | 1977 | Y | N | - | Y | N | - |
| P 04546 * | U | N | U | U | U | U | U |
| P 04547 * | U | N | U | U | U | U | U |
| P 04548 | 1977 | Y | N | - | Y | N | - |
| P 04551 | 1977 | Y | N | - | Y | N | - |
| P 04553 * | U | N | U | U | U | U | U |
| P 04554 | 1954 | Y | Y | Y | Y | N | - |
| P 04556 | 1954 | Y | Y | Y | Y | N | - |
| P 04558 | 1954 | Y | Y | Y | Y | N | - |
| P 04564 | 1954 | Y | Y | Y | Y | N | - |
| P 04566 | 1954 | Y | Y | Y | Y | N | - |
| P 04568 | 1954 | Y | Y | Y | Y | N | - |
| P 04570 | 1957 | Y | Y | Y | Y | Y | - |
| P 04572 | 1970 | Y | N | - | Y | N | - |
| P 04573 | 1959 | Y | N | - | Y | Y | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|-----------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 04575 | 1956 | Y | N | - | Y | N | - |
| P 04580 | 1954 | Y | Y | Y | Y | N | - |
| P 04582 | 1954 | Y | Y | Y | Y | N | - |
| P 04584 | 1954 | Y | Y | Y | Y | N | - |
| 04585 ** | U | N | U | U | U | U | U |
| P 04586 | 1954 | Y | Y | Y | Y | N | - |
| P 04587 * | U | N | U | U | U | U | U |
| P 04588 | 1954 | Y | N | - | Y | Y | - |
| P 04590 | 1954 | Y | Y | Y | Y | N | - |
| P 04592 | 1954 | Y | Y | Y | Y | N | - |
| P 04594 | 1954 | Y | Y | Y | Y | N | - |
| P 04596 | 1954 | Y | Y | Y | Y | N | - |
| P 04598 | 1954 | Y | N | - | Y | Y | - |
| P 04780 | 1954 | Y | N | - | Y | N | - |
| P 04782 | 1954 | Y | Y | Y | Y | N | - |
| P 04784 | 1954 | Y | Y | Y | Y | N | - |
| P 04786 | 1954 | Y | Y | Y | Y | N | - |
| 04788 ** | U | N | U | U | U | U | U |
| P 04790 | 1954 | Y | Y | N | Y | N | - |
| P 04791 | 1974 | Y | Y | N | Y | N | - |
| P 04792 | 1954 | Y | Y | Y | Y | N | - |
| P 04793 | 1974 | Y | Y | N | Y | N | - |
| P 04794 | 1954 | Y | Y | Y | Y | N | - |
| P 04795 | 1974 | Y | N | - | Y | N | - |
| P 04796 | 1954 | Y | Y | Y | Y | N | - |
| P 04797 | 1974 | Y | Y | N | Y | N | - |
| P 04798 | 1954 | Y | Y | Y | Y | Y | - |
| P 04799 | 1974 | Y | Y | N | Y | N | - |
| P 04850 | 1953 | Y | N | - | Y | N | - |
| P 04851 | 1953 | Y | N | - | Y | N | - |
| P 04852 | 1953 | Y | N | - | Y | N | - |
| P 04855 | 1953 | Y | N | - | Y | N | - |
| P 04856 | 1958 | Y | N | - | Y | N | - |
| P 04857 | 1953 | Y | N | - | Y | N | - |
| P 04858 | 1953 | Y | N | - | Y | Y | - |
| P 04859 | 1953 | Y | N | - | Y | N | - |
| P 04860 | 1953 | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|------------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 04861 | 1953 | Y | N | - | Y | N | - |
| P 04862 | 1953 | Y | N | - | Y | N | - |
| P 04863 | 1953 | Y | N | - | N | - | X |
| P 04864 * | U | N | U | U | U | U | U |
| P 04865 * | U | N | U | U | U | U | U |
| P 04866 | 1953 | Y | N | - | N | - | X |
| P 04867 | 1953 | Y | N | - | N | - | X |
| P 04868 * | U | N | U | U | U | U | U |
| P 04885 | 1979 | Y | Y | N | Y | N | - |
| S 04889 | 1975 | Y | N | - | N | - | X |
| S 04890 | 1968 | Y | N | - | Y | N | - |
| T 04894 | 1940 | Y | N | - | Y | N | - |
| P 04895 * | U | N | U | U | U | U | U |
| P 04896 | 1967 | Y | N | - | Y | N | - |
| P 04897 | 1967 | Y | Y | N | Y | N | - |
| P 04898 | 1967 | Y | Y | N | Y | N | - |
| P 04899 | 1967 | Y | Y | N | Y | N | - |
| P 04899A * | U | N | U | U | U | U | U |
| T 04899B | 1940 | Y | N | - | Y | N | - |
| T 04899C | 1941 | Y | N | - | Y | N | - |
| P 04899D | 1940 | Y | N | - | Y | N | - |
| T 04899E | 1940 | Y | N | - | Y | N | - |
| T 04899F | 1982 | Y | N | - | N | - | X |
| T 04899G | U | Y | N | - | Y | N | - |
| P 04902 * | U | N | U | U | U | U | U |
| S 04903 | 1961 | Y | N | - | Y | N | - |
| P 04904 | 1960 | Y | N | - | N | - | X |
| T 04905 | 1958 | Y | N | - | N | - | X |
| T 04906 | 1956 | Y | N | - | N | - | X |
| 04907 ** | U | N | U | U | U | U | U |
| 04908 ** | U | N | U | U | U | U | U |
| P 04912 | 1967 | Y | N | - | N | - | X |
| P 04913 | 1967 | Y | N | - | Y | N | - |
| S 04914 | 1964 | Y | N | - | N | - | X |
| T 04915 | 1940 | Y | N | - | Y | N | - |
| T 1A125 | U | Y | N | - | Y | N | - |
| T 1A127 | U | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|-----------|-------------------|----------|-------------|------------|----------------|------------|--------|
| T Annex-1 | U | Y | N | - | Y | N | - |
| T Annex-2 | U | Y | N | - | Y | N | - |
| T Annex-3 | U | Y | N | - | Y | N | - |
| T DEI-028 | U | Y | N | - | Y | N | - |
| T DEI-029 | U | Y | N | - | Y | N | - |
| T DEI-038 | U | Y | N | - | N | - | X |
| T DEI-040 | U | Y | N | - | Y | N | - |
| T DEI-041 | U | Y | N | - | N | - | X |
| T DEI-058 | U | Y | N | - | Y | N | - |
| T DEI-059 | U | Y | N | - | N | - | X |
| T DEI-066 | U | Y | N | - | N | - | X |
| T DEI-077 | U | Y | N | - | N | - | X |
| T DEI-086 | U | Y | N | - | N | - | X |
| T DEI-090 | U | Y | N | - | N | - | X |
| T DEI-091 | U | Y | N | - | N | - | X |
| T DEI-093 | U | Y | N | - | N | - | X |
| T DEI-098 | U | Y | N | - | N | - | X |
| T DEI-099 | U | Y | N | - | N | - | X |
| T DEI-100 | U | Y | N | - | N | - | X |
| T DEI-101 | U | Y | N | - | N | - | X |
| T DEI-103 | U | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

CSU / SCHOONOVER/PRESTON PARCEL 1 – ASBESTOS SURVEY HISTORY

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|----------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 05324 | 1989 | Y | N | - | Y | N | - |
| P 05330 | 1989 | Y | N | - | Y | N | - |
| P 05331 | 1989 | Y | N | - | Y | N | - |
| P 05369 | 1989 | Y | N | - | N | - | X |
| P 05398 | U | Y | N | - | N | - | X |
| P 05447 | U | Y | N | - | N | - | X |
| P 05460 | 1989 | Y | N | - | Y | N | - |
| P 05481 | 1989 | Y | N | - | Y | N | - |
| P 05492 | 1989 | Y | N | - | Y | N | - |
| P 05656 | 1987 | Y | N | - | N | - | X |
| P 05669 | 1987 | Y | N | - | N | - | X |
| P 05713 | U | Y | N | - | N | - | X |
| P 05716 | 1987 | Y | N | - | N | - | X |
| P 05718 | 1987 | Y | N | - | N | - | X |
| P 05719 | 1987 | Y | N | - | N | - | X |
| P 05721 | 1987 | Y | N | - | N | - | X |
| P 05723 | 1987 | Y | N | - | N | - | X |
| P 05747 | 1987 | Y | N | - | N | - | X |
| P 05767 | 1990 | Y | N | - | Y | N | - |
| P 05776 | 1990 | Y | N | - | Y | N | - |
| P 05777 | 1990 | Y | N | - | N | - | X |
| P 05810 | 1990 | Y | N | - | Y | N | - |
| P 05812 | 1990 | Y | N | - | N | - | X |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

CSU / FREDERICKS PARK PARCEL 1 - ASBESTOS SURVEY HISTORY

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|----------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 05841 | 1981 | Y | N | - | Y | N | - |
| P 05842 | 1981 | Y | N | - | Y | N | - |
| P 05843 | 1981 | Y | N | - | Y | N | - |
| P 05844 | 1981 | Y | N | - | Y | N | - |
| P 05845 | 1981 | Y | N | - | Y | N | - |
| P 05846 | 1981 | Y | N | - | Y | N | - |
| P 05847 | 1981 | Y | N | - | Y | N | - |
| P 05849 | 1981 | Y | N | - | Y | N | - |
| P 05850 | 1981 | Y | N | - | Y | N | - |
| P 05851 | 1981 | Y | N | - | Y | N | - |
| P 05852* | U | N | U | U | U | U | U |
| P 05854 | 1981 | Y | N | - | Y | N | - |
| P 05855 | 1981 | Y | N | - | Y | N | - |
| P 05866 | 1981 | Y | N | - | Y | N | - |
| P 05867 | 1981 | Y | N | - | Y | N | - |
| P 05868 | 1981 | Y | N | - | Y | N | - |
| P 05870 | 1981 | Y | N | - | Y | N | - |
| P 05871 | U | Y | N | - | N | - | X |
| P 05872 | 1981 | Y | N | - | Y | N | - |
| P 05873 | 1981 | Y | N | - | Y | N | - |
| P 05874 | 1981 | Y | N | - | Y | N | - |
| P 05875* | U | N | U | U | U | U | U |
| P 05876 | 1981 | Y | N | - | Y | N | - |
| P 05877* | U | N | U | U | U | U | U |
| P 05879 | 1981 | Y | N | - | Y | N | - |
| P 05880 | 1981 | Y | N | - | Y | N | - |
| P 05881 | 1981 | Y | N | - | Y | N | - |
| P 05882 | 1981 | Y | N | - | Y | N | - |
| P 05883 | 1981 | Y | N | - | Y | N | - |
| P 05885 | 1981 | Y | N | - | Y | N | - |
| P 05886 | 1981 | Y | N | - | Y | N | - |
| P 05887 | 1981 | Y | N | - | Y | N | - |
| P 05889 | 1981 | Y | N | - | Y | Y | - |
| P 05890 | 1981 | Y | N | - | Y | N | - |
| P 05893 | 1981 | Y | N | - | Y | N | - |
| P 05896 | 1981 | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

CSU / FREDERICKS PARK PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|----------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 05897 | 1981 | Y | N | - | Y | N | - |
| P 05898 | 1981 | Y | N | - | Y | N | - |
| P 05899 | 1981 | Y | N | - | Y | N | - |
| P 05900 | 1981 | Y | N | - | Y | N | - |
| P 05901 | 1981 | Y | N | - | Y | N | - |
| P 05903 | 1981 | Y | N | - | Y | N | - |
| P 05904 | 1981 | Y | N | - | Y | N | - |
| P 05905 | 1981 | Y | N | - | Y | N | - |
| P 05907 | 1981 | Y | N | - | Y | N | - |
| P 05909 | 1981 | Y | N | - | Y | N | - |
| P 05911 | 1981 | Y | N | - | Y | N | - |
| P 05912 | 1981 | Y | N | - | Y | N | - |
| P 05913 | 1981 | Y | N | - | Y | N | - |
| P 05914 | 1981 | Y | N | - | Y | N | - |
| P 05917 | 1981 | Y | N | - | Y | N | - |
| P 05918 | 1981 | Y | N | - | Y | N | - |
| P 05919 | 1981 | Y | N | - | Y | N | - |
| P 05920 | 1981 | Y | N | - | Y | N | - |
| P 05921 | 1981 | Y | N | - | Y | N | - |
| P 05923 | 1981 | Y | N | - | Y | N | - |
| P 05925 | 1981 | Y | N | - | Y | N | - |
| P 05926* | U | N | U | U | U | U | U |
| P 05927 | 1981 | Y | N | - | Y | N | - |
| P 05932 | 1981 | Y | N | - | Y | N | - |
| P 05934 | 1981 | Y | N | - | Y | N | - |
| P 05935 | 1981 | Y | N | - | Y | N | - |
| P 05936 | 1981 | Y | N | - | Y | N | - |
| P 05938 | 1981 | Y | N | - | Y | N | - |
| P 05941 | 1981 | Y | N | - | Y | N | - |
| P 05942 | 1981 | Y | N | - | Y | N | - |
| P 05943 | 1981 | Y | N | - | Y | N | - |
| P 05944 | 1981 | Y | N | - | Y | N | - |
| P 05945 | 1981 | Y | N | - | Y | N | - |
| P 05946 | 1981 | Y | N | - | Y | N | - |
| P 05947 | 1981 | Y | N | - | Y | N | - |
| P 05948 | 1981 | Y | N | - | Y | N | - |
| P 05951 | 1981 | Y | N | - | Y | N | - |
| P 05953 | 1981 | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found

CSU / FREDERICKS PARK PARCEL 1 - ASBESTOS SURVEY HISTORY (CONTINUED)

| BUILDING | CONSTRUCTION DATE | SURVEYED | FRIABLE ACM | RATING 1-5 | NONFRIABLE ACM | RATING 1-5 | NO ACM |
|----------|-------------------|----------|-------------|------------|----------------|------------|--------|
| P 05954 | 1981 | Y | N | - | Y | N | - |
| P 05957 | 1981 | Y | N | - | Y | N | - |
| P 05958* | U | N | U | U | U | U | U |
| P 05959 | 1981 | Y | N | - | Y | N | - |
| P 05960 | 1981 | Y | N | - | Y | N | - |
| P 05961 | 1981 | Y | N | - | Y | N | - |
| P 05962 | 1981 | Y | N | - | Y | N | - |
| P 05963 | 1981 | Y | N | - | Y | N | - |
| P 05964 | 1981 | Y | N | - | Y | N | - |
| P 05965 | 1981 | Y | N | - | Y | N | - |
| P 05967 | 1981 | Y | N | - | Y | N | - |
| P 05968* | U | N | U | U | U | U | U |
| P 05969* | U | N | U | U | U | U | U |
| P 05970 | 1981 | Y | N | - | Y | N | - |
| P 05971 | 1981 | Y | N | - | Y | N | - |
| P 05972 | 1981 | Y | N | - | Y | N | - |
| P 05973 | 1981 | Y | N | - | Y | N | - |

LEGEND: IP = In progress
 Y = Yes
 N = No
 U = Unknown

X = Applicable
 - = Not applicable
 ACM = Asbestos-containing material
 Rating 1-5 = ACM of immediate concern

HLA PROJECT NO. 25894

* Not a structure/No survey performed
 ** Unknown structure/No building found