

Table 1. Priority Reuse Parcels Environmental Baseline Survey CSUMB Parcel Fort Ord, California

California State University, Monterey Bay
Brostrom Park Family Housing Area
Thorson Village Family Housing Area
Monterey Peninsula Unified School District
York Road
McKinney Homeless Act Areas
University of California, Santa Cruz
Hayes Park Housing Area
Stilwell Housing Area
Fritzsche Army Airfield (City of Marina)
Monterey County Parks
Patton Park Housing Area
Abrams Park Housing Area

Table 2. Fort Ord and COE EBS Points-of-Contact Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Fort Ord Points-of-Contact

Program
Asbestos Management Program Lead-Based Paint Assessments Radon Surveys PCB transformers CERFA
UXO Surveys Range Control Former Range Control
Former 49th Fort Ord EOD Unit Fort Ord Fire Department
RI/FS Program RCRA Program UST Program Radiological Surveys

COE Points-of-Contact

Name	Program
Ms. Linda Findley-Miller	Asbestos Management Program
Mr. Dan McMindes	Underground/Aboveground Storage Tanks

Table 3. Radon Survey Results Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Building	Occupant	Previous	Retest
Number	Address	Radon Level	Radon Level*
5640G	Schoonover Park	4.2	0.8 pCi/l
4792	4/21st INF	14.0	2.5 pCi/l

^{*} Maximum radon level measured. pCi/l Picocuries per liter of air.

Table 4. Radiological Surveys in Buildings Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Building Numbers	Building Numbers
1421	4554
1422	4556
1423	4558
1424	4564
1427	4566
1477	4568
1483	4580
1489	4582
1649	4584
1674	4586
3570	4590
3574-A	4592
3574-B	4594
3574-C	45 96
3574	4782
3575	4784
3621	4786
3640	4791
3643	4792
3708	4794
3713	4795
3762-A	4796
3762	4799
	4886
	~~~~

### Table 5. Underground Storage Tank Status Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Building	UST No.	Contents	Size (Gallons)	Year Installed	Date Removed	Test 92	Res	ults 90	Closure Granted
1400	4	Diesel	200		0/04				V.,
1426	1		200		2/91				Yes
1426	2 3	Diesel Diesel	200		2/91				Yes
1426			200	4054	2/91		n	N.T	Yes
1434	1	Stoddard	9,000	1951	Inplace		P F	N	No
1434	2	Stoddard	3,000	1951	Inplace		Г	N	No
1434	3	Stoddard	3,000	1951	3/92		<b>N</b> T	N.T	Yes
1480	1	Waste Oil	550	1976	9/92	т	N	N	Yes
1482	1	Waste Oil	550	1976	Inplace	P	P	P	No
1483	1	Diesel	2,500	1976	6/94	P	p	P	No
1483	2	Waste Oil	550	1976	9/92		N	P	No
1487	1	Waste Oil	550	1976	3/92		-	-	Yes
1489	1	Diesel	1,500	1976	Inplace	P	P	F	No
1489	2	Waste Oil	550	1976	Inplace	P	P	P	No
1492	1	Waste Oil	550	1976	Inplace	_	P	P	No
1494	1	Waste Oil	550	1976	Inplace	P	P	P	No
1495	1	Diesel	2,000	1976	Inplace	P	P	P	No
1495	2	Waste Oil	550	1976	Inplace	P	P	P	No
1497	1	Diesel	12,000	1976	Inplace	P	P	P	No
1497	2	Diesel	25,000	1976	Inplace	P	P	P	No
1497	3	Diesel	25,000	1976	Inplace	P	P	P	No
1497	4	Unlead	25,000	1976	Inplace	P	P	P	No
1497	5	Unlead	25,000	1976	Inplace	P	P	P	No
1636	1	Waste Oil	1,000	1985	5/92			P	Yes
1638	1	$\mathbf{Diesel}$	1,000	1978	3/92				Yes
1670	1	Unlead	12,000	1941	Inplace	P	P	N	No
1670	2	Diesel	12,000	1941	Inplace	P	P	P	No
1680	1	Waste Oil	1,000	1983	Inplace	P	P	P	No
1685	1	$\mathbf{Diesel}$			1984				No
1685	2	Diesel			1984				No
1685	3	Diesel			1984				No
1689	1	Waste Oil	1,000	1985	3/92				Yes
1697	1	Diesel	1,000	1981	6/94	P	P	P	No
1697	2	Waste Oil	550	1981	3/92				No
1699	1	Waste Oil	550	1981	3/92				Yes
3576	1	$\mathbf{Diesel}$	15,000	1980	3/92				Yes
3582	1	Diesel	15,000	1982	3/92				Yes
3585	1	${f Diesel}$	30,000	1982	3/92				Yes
3589	1	$\mathbf{Diesel}$	15,000	1982	3/92				Yes
3595	1	Diesel	15,000	1982	3/92				Yes
3599	1	Diesel	1,000	1979	3/92				Yes
3621	1	Diesel	8,000	1977	Inplace	P	P	P	No
3621	2	Waste Diese		1977	Inplace	P	P	P	No
3636	1	Diesel	8,000	1977	Inplace	P	P	P	No

December 16, 1994 Version 2.0

### Table 5. Underground Storage Tank Status Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Building	UST No.	Contents	Size (Gallons)	Year Installed	Date Removed	Test 92	Res	ults 90	Closure Granted
						·····			<del></del>
			_		_				
3636	2	Waste Diese		1977	Inplace	P	P	P	No
3641	1	Diesel	10,000	1977	Inplace	P	P	P	No
3641	2	Waste Diese		1977	Inplace	P	P	P	No
3702	1	Diesel	2,000	1958	3/92				Yes
3 <b>7</b> 03	1	Diesel	3,000	1962	3/92				Yes
3723	1	Diesel	1,000	1984	5/92		N	N	Yes
3766	1	Unlead	5,000	1 <del>94</del> 1	3/91				Yes
3766	2	Waste Oil	5,000	1941	3/91				Yes
3771	1	$\operatorname{Unlead}$	5,000	1941	3/91				Yes
3771	2	Diesel	5,000	1941	3/91				Yes
3775	1	Unlead	5,000	1941	3/91				Yes
3775	2	Diesel	5,000	1941	3/91				Yes
3803	1	NA	1,500	1942	3/91				No
3803	2	NA	1,500	1942	3/91				No
3803	3	NA	5,000	1942	3/91				No
3866	1	Diesel	Unknown	1941	1/90				Yes
3871	1	Unlead	6,500	1942	2/91				Yes
4526	1	Diesel	5,000	1953	3/91				Yes
4526	2	Diesel	5,000	1953	3/91				Yes
4526	3	Diesel	5,000	1953	3/91				Yes
4526	4	Unlead	5,000	Undoc.	3/91				Yes
4528	1	Diesel	550	1980	Inplace	P	P		No
4534	1	Waste Oil	550	Undoc.	3/91	T	I		No
4538	1	Diesel	2,000	1976	Inplace	P	P	P	No
4538	2	Waste Oil	550		-	P	P	P	
4540		Waste Oil		1976	Inplace	r			No Van
	1		550	1976	9/92	D	N	P	Yes
4543	1	Waste Oil	550	1976	Inplace	P	P	P	No
4544	1	Diesel	2,000	1976	Inplace	P	P	P	No
4544	2	Waste Oil	550	1976	Inplace	P	P	P	No
4545	1	Diesel	20,000	1976	Inplace	P	P	P	No
4545	2	Diesel	20,000	1976	Inplace	P	P	P	No
4545	3	Unlead	20,000	1976	Inplace	P	P	P	No
<b>4</b> 547	1	Waste Oil	550	1976	Inplace	P	P	P	No
4548	1	Waste Oil	550	1976	9/92		N	P	Yes
4548	2	Diesel	2,000	1976	Inplace	P	P	P	No
4580	1	Diesel	3,500	195 <b>4</b>	4/92				$\mathbf{Yes}$
4590	1	Diesel	3,000	1954	4/92				No
4782	1	Diesel	3,500	1954	<b>4</b> /92				Yes
<b>47</b> 92	1	Diesel	3,500	1954	3/92				Yes
4850	1	Unlead	5,000	1952	2/91				Yes
4850	2	Unlead	5,000	1952	2/91				Yes
4850	3	Unlead	5,000	1952	2/91				Yes

A36156-H December 16, 1994 Version 2.0

### Table 5. Underground Storage Tank Status Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Building	UST No.	Contents	Size (Gallons)	Year Installe	Date d Removed	Tes 92	t Res 91	ults 90	Closure Granted
		<del></del>							
<b>48</b> 52	1	Unlead	5,000	1952	2/91				Yes
4852	2	Unlead	5,000	1952	2/91				Yes
4852	3	Unlead	5,000	1952	2/91				Yes
4855	1	Waste Oil	550	1965	Undoc. Remova	al			No
4861	1	Diesel	5,000	1952	2/91				Yes
4861	2	Diesel	5,000	1952	2/91				Yes
4861	3	Diesel	5,000	1952	2/91				Yes
4885	1	Diesel	550	1978	Inplace	P	P	P	No
4885	2	Waste Oil	550	1978	Inplace	P	P	N	No
5871	1	Diesel	300	1983	Inplace	P	P	P	No

P Pass.

F Fail.

N No test results available.

NA Information not available.

## Table 6. Aboveground Storage Tank Status Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Building Number	Contents	Size (Gallons)	Berm	Secondary Containment
3700	Diesel	250	Yes	No
<b>490</b> 0	Waste Oil	500	Yes	No
4901	Diesel	400	Yes	No

Table 7. Solid Waste Management Units (SWMUs)
Environmental Baseline Survey
CSUMB Parcel
Fort Ord, California

Site No.	SWMU Name	SWMU Type	NPL Site No.	Parcel
FTO-004	707th Maintenance Bn, A, B, and C Cos.	Container Storage	14	CSUMB
FTO-005	13th Engineer Bn Motor Pool	Container Storage	22	CSUMB
FTO-013	Building 1442 Autoclave	Thermal Treatment	17	CSUMB
FTO-015	PCB Storage Area	Container Storage	15	CSUMB
FTO-018	Pesticide Mixing Area	Container Storage	15	CSUMB
FTO-019	AAFES-Economy Cleaners UST for Product Solvent	Container Storage	38	CSUMB
FTO-023	TASC Graphics Shop	Temp, Container Storage	18	CSUMB
FTO-025	14th Engineer Battalion Motor Pool	Temp, Container Storage	22	CSUMB
FTO-026	127th Signal Company Motor Pool	Temp, Container Storage	22	CSUMB
FTO-035	3rd Brigade Consolidated Motor Pool	Temp. Container Storage	22	CSUMB
FTO-040	DOL Temporary Motor Pool	Temp. Container Storage	18	CSUMB
FTO-044	123rd AVN Battalion, E Company Motor Pool	Temp, Container Storage	15	CSUMB
FTO-045	237th Medical Detachment Motor Pool	Temp. Container Storage	15	CSUMB
FTO-048	6th/8th Field Artillery Battalion Motor Pool	Temp. Container Storage	17	CSUMB
FTO-049	7th/15th Field Artillery Battalion Motor Pool	Temp. Container Storage	17	CSUMB
FTO-050	2nd Battalion, 62nd Air Defense Artillery Motor Pool	Temp. Container Storage	17	CSUMB
FTO-051	5/15th Field Artillery Battalion Motor Pool	Temp. Container Storage	17	CSUMB
FTO-052	7th Military Police Company Motor Pool	Temp. Container Storage	18	CSUMB
FTO-053	123 Regiment AVN Regiment, E Company Motor Pool	Temp. Container Storage	18	CSUMB
FTO-054	107th Medical Battalion Motor Pool	Temp. Container Storage	23	CSUMB
FTO-056	707th SPT Battalion Organizational Motor Pool	Temp. Container Storage	18	CSUMB
FTO-057	571st Military Police Company Motor Pool	Temp. Container Storage	18	CSUMB
FTO.058	7610t Chamical Commons Maten Deal	Town Contains Classes	07	COLTA AD

Harding Lawson Associates

N32375-H December 16, 1994 Version 2.0

### Table 8. Definitions of CERFA Categories Environmental Baseline Survey CSUMB Parcel Fort Ord, California

- CERFA Parcel Portion of the installation real property for which [the CERFA] investigation revealed no evidence of storage for one year or more, release, or disposal of CERCLA hazardous substances, petroleum, or petroleum derivatives and no evidence of being threatened by migration of such substances. CERFA parcels include areas where PCB-containing equipment is in operation, but there is not evidence of release. CERFA parcels also include any portion of the installation that once contained related environmental, hazard, or safety issues including unexploded ordnance (UXO) located on firing ranges or impact areas, radon, stored (not in use) PCB-containing equipment, products that contained radionuclides being used for their intended purposes, asbestos contained within building materials, and lead-based paint applied on building material surfaces, but that has since been removed or fully remediated.
- CERFA Parcel with Qualifier(s) A portion of the installation real property for which [the CERFA] investigation reveals no evidence of storage for one year or more, release, or disposal of CERCLA hazardous substance, petroleum, or petroleum derivatives and no evidence of being threatened by migration of such substances. The parcel does however contain related environmental, hazard, or safety issues including UXO located on firing ranges or impact areas, radon, radionuclides contained within products being used for their intended purposes, asbestos contained within building materials, lead-based paint applied to building material surfaces, or stored (not in use) PCB-containing equipment.
- CERFA Disqualified Parcel Portion of the installation real property for which [the CERFA] investigation reveals evidence of a release, disposal, or storage for more than one year of a CERCLA hazardous substance, petroleum, or petroleum derivative; or a portion of the installation is threatened by such a release or disposal. CERFA disqualified parcels also include any portion of the installation where PCB, asbestos containing material, lead-based paint residue, or any ordnance has been disposed of, and any locations where chemical ordnance has been stored. Additionally, CERFA disqualified parcels include any areas in which CERCLA hazardous substances or petroleum products have been released or disposed and subsequently fully remediated.
- CERFA Excluded Parcel A portion of the installation real property retained by the Department of Defense, and therefore not explicitly investigated for CERFA.
   CERFA-excluded parcels also include any portions of the installation that have already been transferred by deed to a party outside the federal government, or by transfer assembly to another federal agency. No CERFA excluded parcels were identified at Fort Ord.

Source: Arthur D. Little, Inc. (ADL), 1994. Community Environmental Response Facilitation Act (CERFA) Report, Fort Ord, Monterey, California. Contract No. DAAA15-91-D-0016, April 8, Revision 1 (Final).

### Table 9. Basewide NPL Site Summary Table Environmental Baseline Survey CSUMB, Monterey Bay, Parcel Fort Ord, California

Site Number	Site Name	Category
1	Ord Village Sewage Treatment Plant	No Action
2	Main Garrison Sewage Treatment Plant	Remedial Investigation
3	Beach Trainfire Ranges	Remedial Investigation
4	Beach Stormwater Outfalls	No Action
5	Range 36A	Remedial Investigation
6	Range 39 (Abandoned Car Dump)	Interim Action
7	Ranges 40 and 41 (Fire Demonstration Area)	No Action
8	Range 49 (Molotov Cocktail Range)	Interim Action
9	Range 39 (FFE Training Area)	Remedial Investigation
10	Burn Pit	Interim Action
11	AAFES Fueling Station	No Action
12	Low Meadow, DOL Yard, Cannibalization Yard	Remedial Investigation
13	Railroad Right-of-Way	No Action
14	707th Maintenance Facility	Interim Action
15	DEH Yard	Interim Action
16	DOL Maintenance Yard and Pete's Pond	Remedial Investigation
17	1400 Block Motor Pool	Remedial Investigation
18	1600 Block Motor Pool	No Action
19	2200 Block Facility	No Action
20	South Parade Ground and 3800 and 519 Motor Pools	Interim Action
21	4400/4500 Block Motor Pool, East	Interim Action
22	4400/4500 Block Motor Pool, West	Interim Action
23	3700 Block Motor Pool Complex	Interim Action
24	Old DEH Yard	Interim Action*
25	Former DRMO	No Action

A36156-H December 16, 1994 Version 2.0 Harding Lawson Associates1 of 2

### Table 9. Basewide NPL Site Summary Table Environmental Baseline Survey CSUMB, Monterey Bay, Parcel Fort Ord, California

Site Number	Site Name	Category
26	Sewage Pump Stations	No Action
27	Army Reserve Motor Pool	No Action
28	Barracks and Main Garrison Area	No Action
29	DRMO	No Action
30	Drive Training Area	Interim Action
31	Former Dump Site	Remedial Investigation
32	East Garrison Sewage Treatment System	No Action
33	Golf Course	No Action
34	FAAF Fueling Facility	Interim Action
35	FAAF Aircraft Cannibalization Yard	No Action
36	FAAF Sewage Treatment Plant	No Action
37	Trailer Park Maintenance Shop	No Action
38	AAFES Dry Cleaners	No Action
39	Impact Area	Remedial Investigation
40	FAAF Helicopter Defueling Areas	Interim Action*
41	Crescent Bluff Fire Drill Area	Interim Action*

^{*} Site categories may change as additional information is received from ongoing investigation.

## Table 10. Adjacent Property NPL Sites, OEW Areas and SWMUS Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Site Name	Location	Site Description
NPL Sites		
Site 2: Main Garrison Sewage Treatment Plant	0.5 mile northwest	Soil and groundwater contamination: lead in soil, chlorinated solvents in groundwater
Site 3: Beach Trainfire Area	0.6 mile west	Soil contamination: metals
Site 4: Beach Stormwater Outfalls	0.75 mile west	Potential release of hazardous materials; awaiting risi
Site 10: Burn Pit	0.25 mile southwest	Soil contamination: TPH, BTEX, VOC. Potential groundwater contamination, not confirmed
Site 11: AAFES Fueling Station	0.25 mile southwest	Soil contamination: hydrocarbons and lead
Site 12: DOL Automotive & Cannibalization Yard	0.25 mile west	Soil and groundwater contamination: lead in soil, chlorinated solvents in groundwater
Site 13: Railroad Right-of-way	0.25 mile west	No unacceptable risk associated with chemicals in so or groundwater
Site 16: DOL Maintenance Yard and Pete's Pond	North/East boundaries	Soil contamination: TPH, BTEX, VOCs, metals, lands debris (UXO)
Site 19: 2200 Block Facility	0.25 mile north	Soil contamination: chlordane, unknown hydrocarbo
Site 20: South Parade Ground, 3800 & 519th Motor Pools	West boundary	Soil contamination; low chromium, organics in soil gas, potential landfill locations
Site 21: 4400/5500 Motor Pool, East Block	South boundary	Soil contamination: oil and grease, metals
Site 22: 4400/5500 Motor Pool, West Block	South boundary	Soil contamination: high boiling hydrocarbons
Site 24: Old DEH Yard	South/West boundary	Soil contamination: high boiling hydrocarbons
Site 25: Former DRMO Site	North boundary	No unacceptable risk associated with chemicals in so or groundwater
Site 27: Army Reserve Motor Pool	0.45 mile northeast	No unacceptable risk associated with chemicals in so or groundwater
Site 28: Barracks and Main Garrison	0.5 mile northeast	No unacceptable risk associated with chemicals in so or groundwater
Site 29: East Garrison DRMO	1.0 mile east	No unacceptable risk associated with chemicals in so or groundwater
Site 30: Driver Training Area	0.9 mile east	Soil contamination: TPH, BTEX, VOCs
Site 32: East Garrison Sewage Treatment Plant	0.8 mile east	No unacceptable risk associated with chemicals in so or groundwater
Site 34: FAAF Fueling Facility	0.8 mile north	Soil contamination: hydrocarbons
Site 35: Aircraft Cannibalization Yard	0.65 mile north	No unacceptable risk associated with chemicals in so or groundwater
Site 40: FAAF Defueling Area	1.0 mile north	Soil contamination: methane, VOCs, hydrocarbons, unknown hydrocarbons

A36156-H December 16, 1994 Version 2.0

# Table 10. Adjacent Property NPL Sites, OEW Areas and SWMUS Environmental Baseline Survey CSUMB Parcei Fort Ord, California

Site Name	Location	Site Description
Operable Unit 1	0.75 mile north	Soil and groundwater contamination: hydrocarbons, solvents; remediation being conducted by Ft. Ord
Operable Unit 2, Fort Ord Landfills	North Boundary	Soil and groundwater contamination: TCE, landfill debris
DEW Locations		
Machine Gun Square 1	0.5 mile west	No confirmed hazards; Huntsville to verify
Machine Gun Square 2	0.35 mile west	No confirmed hazards; Huntsville to verify
Machine Gun Square 5	500 feet east	No confirmed hazards; Huntsville to verify
Machine Gun Square 7	0.18 mile south	No confirmed hazards; Huntsville to verify
Mortar Square 1	0.8 mile north	No confirmed hazards: Huntsville to verify
Mortar Square 2	0.8 mile north	No confirmed hazards; Huntsville to verify
Mortar Square 3	0.8 mile north	No confirmed hazards; Huntsville to verify
Mortar Square 4	400 feet south	No confirmed hazards; Huntsville to verify
Mortar Square 5	0.45 mile south	No confirmed hazards; Huntsville to verify
Mine & Booby Trap Area 1	0.75 mile north	Sampling completed, no OEW found
Mine & Booby Trap Area 6	0.35 mile southwest	No confirmed hazards: Huntsville to verify
Firing Point 1	0.1 mile south	No confirmed hazards; Huntsville to verify
Chemical, Biological and Radiological Test Area 1	400 feet south	Sampling completed, no OEW found
Chemical, Biological and Radiological Test Area 2	0.4 mile southeast	Sampling completed, no OEW found
Recoilless Rifle Training Area	0.6 mile southwest	Sampling completed, no OEW found
Parker Flats Practice Mortar Ranges	0.8 mile south	No confirmed hazards: Huntsville to verify
Sinkhole Practice Mortar Range	0.18 mile south	Sampling completed, OEW found, clearance underwa
Fritzsche 3.5-inch Rocket Site	0.4 mile northeast	No confirmed hazards: Huntsville to verify
Machine Gun Proficiency Training Area	North boundary	No confirmed hazards; Huntsville to verify
Imjin Road Practice Mortar Range	0.45 mile north	Sampling completed, no OEW found
Flame Thrower Range 1	0.75 mile north	Sampling completed, no OEW found
75mm Pack Howitzer Firing Area	0.7 mile north	No confirmed hazards; Huntsville to verify
Storage Yard (Landmine)	250 feet north	No confirmed hazards; Huntsville to verify
Molotov Cocktail Range (Range 49)	0.9 mile south	Sampling completed, no OEW found
Pete's Pond	North boundary	Sampling completed, no OEW found

A36156-H December 16, 1994 Version 2.0

### Table 10. Adjacent Property NPL Sites, OEW Areas and SWMUS Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Site Name	Location	Site Description	
			=

### Solid Waste Management Unit (SWMU) Locations

SWMU Name	Location	Site Description
FTO-001 Abandoned Fire Training Pit	0.75 mile north	Groundwater currently being remediated by HLA
FTO-002 Abandoned Landfill	North boundary	Soil and groundwater contamination: TCE, landfill debris
FTO-3 FAAF Sewage Treatment Plant	0.8 mile north	Closed and demolished
FTO-006 HHC Calvary Regiment Pool, Building 527	0.8 mile north	Container storage, no longer in existence
FTO-007 Cannibalization Area	0.25 mile west	Storage yard for deadlined vehicles and vehicle parts
FTO-008 DRMO Hazardous Waste Storage Yard	0.8 mile east	Container storage area, no evidence of releases
FTO-009 DRMO PCB Storage, Bldg T-111	1.0 mile east	Waste transformer oil with >5 ppm PCB, stored in drums in bermed areas
FTO-010 AAFES Service Station	0.25 mile southwest	Waste oil UST, slated for removal
FTO-011 East Garrison Sewage Treatment Plant	0.8 mile east	No impacts based on screening risk evaluation
FTO-012 Main Garrison Sewage Treatment Plant	0.7 mile northwest	Facility shut down in 1989, documented soil and groundwater contamination on site
FTO-014 Fire Training Area	0.25 mile southwest	Area shut down in 1987, documented soil contamination on site
FTO-017 TASC Plastics Shop	North boundary	Container storage area, no evidence of releases
FTO-020 Infectious Waste Incinerator at Bldg 4385	0.2 mile south	Facility shut down in Fall 1992, no evidence of releases
FTO-021 Silver Recovery Unit	0.2 mile south	Facility shut down in Fall 1992, evidence of release of undiluted acetic acid on cement
FTO-022 Abandoned DRMO Site	North boundary	Abandoned storage site, no evidence of releases
PTO-024 519th Maintenance Company Motor Pool	300 feet west	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-027 2/9 Recon Battalion Motor Pool	0.3 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-028 9th Regiment MANCHU Motor Pool	0.3 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-029 9th Regiment HHC Motor Pool	0.3 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases
PTO-030 HHC Aviation Brigade Motor Pool	0.3 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases

## Table 10. Adjacent Property NPL Sites, OEW Areas and SWMUS Environmental Baseline Survey CSUMB Parcel Fort Ord, California

Site Name	Location	Site Description
FTO-031 8th Evacuation Hospital Motor Pool	0.3 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-032 HHC Aviation Brigade Motor Pool	0.3 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-033 1/23 Aviation Regiment, A, B, and C Co. Motor Pool	0.3 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-034 2nd Brigade Consolidated Motor Pool	0.3 mile east	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-036 DOL Heavy Equipment Maintenance Motor Pool	0.1 mile north	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-037 DOL Main Automotive Yard Pool	0.3 mile west	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-038 DOL General Equipment Maintenance Yard	0.3 mile west	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-039 DOL Aircraft Maintenance Motor Pool	0.75 mile north	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-041 590th SS Company Motor Pool	Unknown	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-042 HHC Combat Aviation Brigade Motor Pool	0.75 mile north	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-043 1-123rd AVN Reg. A, B, C, and D Co. Motor Pool	0.75 mile north	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-046 219th Calvary Recon. Flight Maint. Motor Pool	0.75 mile north	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-047 3rd Bn. 123rd AVN Brig. D Co. Flight Maint. Motor Pool	0.75 mile north	Temporary container storage for used vehicle lubricants, no evidence of releases
FTO-055 U.S. Army Reserve Center Motor Pool	0.45 mile northeast	Temporary container storage for used vehicle lubricants, no evidence of releases